Seat No.: _____ Enrolment No._____


GUJARAT TECHNOLOGICAL UNIVERSITY

Diploma Engineering - SEMESTER-I • EXAMINATION - WINTER • 2014

•		Fode: 310029 Date: 26-12-2014 Mame: Engineering Drawing	
•	: 02:	30 pm - 05:30 pm Total Marks: 70	
	1. 2. 1. 3. 1	Attempt any five questions. Make suitable assumptions whrever necessary. Figures to the right indicate full marks. English version is considered to be Authentic.	
Q.1		A pictorial view of an object as shown in fig1. Draw its following views using FIRST ANGLE PROJECTION METHOD. (a) Elevation from X-direction (b) Plan (c) LHS view.	14
Q.2	(a)	Draw an ellipse having major axis and minor axis 120mm and 80mm	07
	(b)	respectively with concentric circle method. Construct a regular heptagon having side of 40 mm using universal circle method.	07
	(b)	OR Construct a regular pentagon having side of 35 mm using three circle method.	07
Q.3	(a) (b)	Name the engineering drawing instruments and state their uses. A line AB is 90 mm long is inclined at 30° to H.P. the top view of line AB makes an angle of 30° to XY. The end A is 10 mm above H.P. and 20 mm in front of V.P. Draw projections of line and find out true inclination of line with V.P.	07 07
0.0		OR	
Q.3	(a)	Draw cycloid for a circle of 60 mm diameter taking stating poin 'P' at bottom of vertical diameter.	07
	(b)	With the help of neat sketches differentiate between Aligned system and Unidirectional system.	07
Q.4	(a)	A pentagonal plane of 30 mm side is resting on H.P. on one of its side which is inclined at 30° to V.P. and plane is inclined at 45° to H.P. Draw the projections	07
	(b)	of plate. With the help of figure show different types of lines such as outline, dotted line, center line, ladder line, Section line, dimension line, extension line etc. OR	07
Q. 4	(a) (b)	Fig2 shows two views of an object. Draw isometric view. A pentagon plate having side of 25 mm is resting on one its side on H.P. and it makes 30° with V.P. surface of the plate is at 45° with H.P.	07 07
Q.5	(a)	Chemical manufacturing company has its expenses as follows: Material cost 40 %, (2) Taxation 20 %, (3) Salaries and welfare expenses 25 %, (4) other expenses 10 %, (5) Profit 5 %. Draw PIE chart.	80
	(b)	Prepare a list of modern methods of storing and reproduction of drawing.	06
		Describe any one. OR	
Q.5	(a)	Draw free hand sketches of the following (1) Wood ruff key (2) Gib head key, (3) Acme thread, (4) Wing nut	08

(b) Explain difference between blue printing and ammonia printing.

06



ગુજરાતી

- પ્રશ્ન.૧ પ્રથમ કોણીય પ્રક્ષેપણની રીત વાંપરી આકૃતિ 1 ના નીચેના દેખાવો દોરો.(1) ૧૪ તીર X ની દિશામાથી જોઈને સામેનો દેખાવ (2) ઉપરનો દેખાવ (3) ડાબી બાજુનો દેખાવ .
- પ્રશ્ન. ર અ મુખ્ય ધરી અને નાની ધરી અનુક્રમે ૧૨૦ મી.મી. અને ૮૦ મીમી હોય એવો **૦૭** ઈલીપ્સ સંકેન્દ્રિત વર્તુળની રીતથી દોરો.
 - બ યુનિવર્સલ વર્તુળની રીત વાપરી ૪૦મીમી બાજુવાળો ષપ્તકોણ દોરો. **૦૭**

અથવા

બ ત્રણ વર્તુળની રીત વાપરી ૩૫મીમી બાજુનો પંચકોણ દોરો.

પ્રશ્ન. 3 અ એંજીન્ચરિંગ ડ્રૉઇંગના સાધનોના નામ આપી તેના ઉપયોગ જણાવો. 0૭

બ ૯૦ મીમીની લંબાઈવાળી રેખા AB આડી સપાટી સાથે 30° નો ખૂણો બનાવે છે. **૦૭** રેખા AB નો ઉપરનો દેખાવ XY સાથે 30° નો ખૂણો બનાવે છે. છેડો A આડી સપાટીથી ૧૦ મીમી ઉપર અને ઊભી સપાટીથી ૨૦ મીમી સામે છે. રેખાના પ્રક્ષેપણ દોરો અને ઊભી સપાટી સાથે સાચો ખૂણો શોધો.

અથવા

પ્રશ્ન. 3 અ ૬૦મીમી વ્યાસવાળા સાઈક્લોડની ૨યના કરો. શરૂવાતનું બિંદુ P ઊભા વ્યાસના ૦૭

09

www.onlinegtu.com

\sim		`	$\overline{}$
તળિટ	บบเ	28	٤٩

લાઇન.

પુશ્વ. ૪

બ	સ્વચ્છ આકૃતિ સાથે એલાઈન્ડ પધ્ધતિ અને યુનીડાયરેકશનલ પધ્ધતિ વચ્ચેનો તફાવત સમજાવો.	0.9
	((રૂલિપા લાગાલા	
અ	30 મી.મી બાજુવાળી પંચકોનીય પ્લેટ તેની એક બાજુ પર આડી સપાટી પરઉભેલ છે.તે બાજુ ઊભી સપાટી સાથે 30° નો ખૂણો બનાવે છે. અને	0.9
	પંચકોનીય પ્લેટ આડી સપાટી સાથે ૪૫° નો ખૂણો બનાવે છે પ્લેટના પ્રક્ષેપણો દોરો.	
બ	30 મી.મી બાજુવાળી ષષ્ટકોણીય પ્લેટ તેની એક બાજુ પર આડી સપાટી પર ઉભેલ છે અને ઊભીસપાટી સાથે 30° નો ખૂણો બનાવે છે પ્લેટ ની સપાટી આડી	೦೨

અથવા

પ્રશ્ન. ૪ અ આકૃતિ-૦૨ મા એક પદાર્થના બે દેખાવો દર્શાવેલ છે તેના સમમિતીય દેખાવ **૦૭** દોરો. બ આકૃતિની મદદથી જુદાજુદા પ્રકારની લાઇન દર્શાવો. આઉટ લાઇન, ડોટેડ **૦૭** લાઇન સેન્ટર લાઇન, લેડર લાઇન,સેક્શન લાઇન,ડાઇમૈન્શન લાઇન,એક્સટેન્શન

સપાટી સાથે ૪૫° નો ખૂણો બનાવે છે, પ્લેટના પ્રક્ષેપણો દોરો.

- પ્રશ્ન. ૫ અ રસાયણ ઉત્પાદન કરતી કંપનીનો ખર્ચ નીચે મુજબ છે: ૧.મટિરિયલ ખર્ચ ૪૦% ૨. કરવેરા ૨૦% ૩. પગાર અને વેલફેર ખર્ચ ૨૫% ૪. અન્ય ખર્ચ ૧૦% ,૫.નફો ૫%. PIE ચાર્ટ દોરો.
 - બ ચિત્રોની જાળવણી અને નકલો તૈયાર કરવા માટે વપરાતી આધુનિક રીતોની os યાદી બનાવી ગમેતે એક નું વર્ણન કરો.

અથવા

પ્રશ્ન.૫ અ નીચે મુજબ એનએ મુક્ત હસ્ત ચિત્ર દોરો. ૧. વૂડરફ કી ૨. ગિબ હેડ કી ૩. એક્મે થેર્ડ ૪. વિંગ નટ બ બ્લૂ પ્રિંટિંગ અને ઍમોનિયા પ્રિંટિંગ વચ્ચે નો તફાવત સમજાવો.